



NOTES:
 1) FOR 220 VOLT OPERATION
 CHANGE WIRING PER FIG. 4
 AND REPLACE 3/4 AMP FUSE
 WITH 3/8 AMP SLOW BLOW

Figure 3 Control Console Schematic